

INSPECTION REPORT <i>QUALITY VALUED. CONFIDENCE DELIVERED</i>	Service	Pre-shipment Inspection	
	Report No.	V-2401596	
	Date Issued	2024-01-22	P 1 / 19

INSPECTION REPORT

1. INSPECTION INFORMATION	
Client:	EWHEELS LLC
Supplier:	Begode
Factory:	Begode
Product:	Mten Mini
P.O. No.:	-
P.O. Quantity:	50pcs
Item No.:	-
Inspection Date:	2024-1-19
Location:	Dongguan City, Guangdong Province
Inspector:	Ben



2. INSPECTION RESULT				
Category	Conform	Not Conform	Pending	Remark
Workmanship/Function	√			

OVERALL CONCLUSION	CONFORM
	Approved by: Sunny Cai

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED


Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 2 / 19

3. REMARK POINT

-	-
---	---

Note

During inspection, 20pcs products were packed into the cartons. 30pcs products were finished and not packed. (For the workmanship, check 30pcs from unpacked lot and 5pcs from packed lot.)



2 The factory claimed that the product does not need the blue front/rear CNC kits.

Check Points (Patton)

1) Battery voltage to full:

Ensure that all the voltage shown on APP can reach the rated voltage 42(+/-0.5V), 80pcs data would be needed, and check another 3 samples to verify the different between app and screen of Multimeter.

Result: For Voltage check, factory only provide 5pcs products with fully charged for inspection, and 1 out of 3pcs inspected samples were found voltage deviation was found between app and screen of Multimeter and 1 out of 5pcs of inspected samples was found the voltage was out of the tolerance of 42+/-0.5V.

Actual Checked Battery Voltage against Voltage by App



Actual Checked:								
Multimeter:	41.53	41.57	41.47					

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 3 / 19

	By App:	41.6	41.6	41.5					
	Battery Voltage check by App								
	41.2	41.8	41.6	41.6	41.6				
2	<p>That tires are mounted centered on the rim, with lubricating compound applied, & that there is no rubbing against fender/shell.</p> <p>Result: The factory did not agree to disassemble the tire to check, so we are not sure whether the Begode applies a tire lubricant.</p>								
									
3	<p>The blue front/rear CNC kits are included in the box.</p> <p>Result: Note</p> <p>The factory claimed that the product does not need The blue front/rear CNC kits</p>								
4	<p>Firmware is updates applied.</p> <p>Result: Actual found</p>								
									
5	<p>Motor rotation to check for bearing/motor issue.</p> <p>Result: Conform</p>								

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 4 / 19



Motor rotation: there is minimum wire oscillation/wobbling in rotation.

Result: Conform

7



All lights work

Result: Conform

8



9

Connectivity to the App.



Result: Conform

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 5 / 19



This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 6 / 19

PHOTO ATTACHMENT

1 products



1



2



3



4



5




6

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 7 / 19



7



8

Mten Mini Specification	
Product Size/尺寸	11 inch
Product Color/产品颜色	Black / 黑色
Product Size/产品尺寸	442*234*146mm
Product Weight/产品重量	14kg
Product Power/产品功率	500W
Product Voltage/产品电压	42V
Product Capacity/产品容量	99wh (40% Yellow, 180wh (50% Black)
Product LCD/产品显示屏	NO
Product Suspension travel/产品减震行程	NO
Product Wireless upgrade/产品无线升级	YES
Product First class speed alarm/产品一级速度报警	12km/h
Product Second class speed alarm/产品二级速度报警	16km/h
Product Free spin speed/产品空载时的速度	30km/h
Product Current limit/产品限流	120A
Product Overvoltage alarm/产品高压报警	42.5V
Product Overheat alarm/产品高温报警	79℃
Product Low voltage warning/产品低电压报警	34V
Product Low power till back alarm/产品低电量报警	33V

9

Mten Mini Specification	
Product Size/尺寸	11 inch
Product Color/产品颜色	Black / 黑色
Product Size/产品尺寸	442*234*146mm
Product Weight/产品重量	14kg
Product Power/产品功率	500W
Product Voltage/产品电压	42V
Product Capacity/产品容量	99wh (40% Yellow, 180wh (50% Black)
Product LCD/产品显示屏	NO
Product Suspension travel/产品减震行程	NO
Product Wireless upgrade/产品无线升级	YES
Product First class speed alarm/产品一级速度报警	12km/h
Product Second class speed alarm/产品二级速度报警	16km/h
Product Free spin speed/产品空载时的速度	30km/h
Product Current limit/产品限流	120A
Product Overvoltage alarm/产品高压报警	42.5V
Product Overheat alarm/产品高温报警	79℃
Product Low voltage warning/产品低电压报警	34V
Product Low power till back alarm/产品低电量报警	33V

10

BT Speaker/蓝牙音箱	NO
Headlight / 前灯	YES
Charger/充电器	42V/1.5A
Headlights/前照灯透明度	2000 lumen
Voltage / 最高电压	42V
Motor power/电机功率	500W
Battery type/电池型号	21700
Battery Capacity / 电池容量	99wh (40% Yellow, 180wh (50% Black)
LCD/显示屏	NO
Suspension travel/减震行程	NO
Wireless upgrade/无线升级	YES
First class speed alarm/一级速度报警	12km/h
Second class speed alarm/二级报警	16km/h
Free spin speed/空载时的速度	30km/h
Current limit / 限流	120A
Overvoltage alarm/高压报警	42.5V
Overheat alarm/高温报警	79℃
Low voltage warning/低电压报警	34V
Low power till back alarm/低电量报警	33V

11



12

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.


INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 8 / 19



13



14



15



16



17



18

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 9 / 19



19



20



21



22



23



24

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 10 / 19



25



26



27



28



29




30

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 11 / 19



31



32



33



34



35



36

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 12 / 19



37



38



39



40



41



42

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 13 / 19



43



44



45



46



47



48

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 14 / 19



49




50



51



52



53



54

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 15 / 19



55



56



57



58



59



60

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED


Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 16 / 19



61



62




63



64



65



66

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 17 / 19




67



68



69



70



71



72

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 18 / 19



73



74



75



76



77



78

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.


INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2401596	
Date Issued	2024-01-22	P 19 / 19



79



80



81



82

***** END OF REPORT *****

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.